

# Product Safety Recall



## Bobbi Bunk Bed

Sold: 1st February 2011  
to 29th November 2011



**Defect:** The Australian Standard for bunk beds requires that the vertical distance between the guard rail and the mark or label indicating the maximum height of the mattress must be at least 160mm. In a batch of 'Bobbi' bunk beds sold between the dates mentioned above, in some instances the location of the label was found to be less than the minimum required distance.

**Hazard:** The inaccurate label positioning may lead to an incorrect size mattress being used on the top bunk which could lead to a falling hazard.

**Action:** Fantastic Furniture will supply a replacement label that indicates the correct vertical distance between the guard rail and the maximum height of the mattress. The top bunk should not be used without adult supervision until the replacement label is affixed.

**Please call the store where you purchased the 'Bobbi' bunk bed or e-mail [customercare@fantasticfurniture.com.au](mailto:customercare@fantasticfurniture.com.au) to arrange for a replacement label to be sent to you.**

**See [www.recalls.gov.au](http://www.recalls.gov.au) for  
Australian product recall information**